






Cubb Tables

Project Table work instructions




Sample BOM




Parts List

X1	Tabletop	- Model Dependant
X2	Oak Leg Side A	- 2531-0291
X2	Oak Leg side B	- 2531-0298
X2	Metal Support End	- 0129-2547
X2	Metal Support Side	- Model Dependant
X1	Mid Leg Support	- Model Dependant
X1	Cross Beam	- Model Dependant
X1	Wire Fixing Kit	- 5938-2741
X1	Fixing Kit	- 5938-2742
X4	Cable Cover	- 1135-0093
X4	Glide	- 1020-2456

Tools Required (not supplied)




1




B C

2





X2
B C H

3




X2
J K
50%



4





5




6




7





8





9




10




11





12





13





14



15



16



17

