




Description	Identifying Picture	Steelcase Service Part #
<b><u>Parts necessary for a relocation or rebuild of a Air 3 Pod</u></b>		
8mm I Line		1381763001SR
Door Back Edge Seal		
Post Fix Seal		1450186001SR

**Additioanl parts that may need to be repalced if lost or damage during teardown or during transport**

Botton Door Track Casting



1381775001SR

Door Stop w/ Soft Pad (pictured)  
bracket and hadware included



1381762001SR

Glass Clamp




1381764001SR

Door Handle Bung



OBAIR32600SR

Corner Bung RH



Corner Bung LH



1381766001SR

Bottom Door Guide Male



Bottom Door Guide Female



1381767001SR

Panel Clips



OBAIR33700SR

Heat Detector



1474858001SR

M8 x 30 Flange Button Hd



OBSYSFIX008SR

M6 Spring T-Nut



OBSYSFIX011SR

<p>M6 x 8 Button Hd</p>		<p>1381774001SR</p>
<p>M6 x 12 Button Hd Skt Screw Znc</p>		
<p>M8 x 12 Hex Sckt</p>		<p>OBSYSFIX013SR</p>
<p>M8 Spring T-Nut</p>		<p>1381773001SR</p>

M8 x 10 Flange Btn Hd



OBSYSFIX059SR

Corner Cover LH



1381784001SR

Corner Cover RH

